

WELL NAME: HILL RANCH 15-09, API #: 071-08474, INSP. # 695109504



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: AREA OF IMPACTED SOIL UNDER DRIVE HEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 5-22-2024.





PHOTO 5: IT APPEARS THAT THE PRODUCED WATER PIT HAS BEEN CLEANED AND THE SECONDARY CONTAINMENT FOR THE PIT MATERIAL STORED ON LOCATION HAS BEEN COMPROMIZED AND THERE IS NO RUN ON PROTECTION IN PLACE TO PREVENT STORM WATER FROM MIXING WITH PIT MATERIAL. INTALL AND REPAIR BERMS PER 1002 SERIES RULES. CA DATE 5-22-2024.





PHOTO 5: IMAGE OF THE COMPROMISED BERM FROM A DIFFERENT ANGLEL.

