

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/22/2024

Document Number:

709100274

FIELD INSPECTION FORMLoc ID 433919 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD State: CO Zip: 80111

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent
Kyle Waggoner		kyle.waggoner@state.co.us	
Parrish, Melissa		mparrish@fundareresources.com	
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT
Krystal Heibel		krystal.heibel@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	Regulatory

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433917	WELL	PR	08/10/2017	OW	123-37844	Razor 21A-2816B	EI
433918	WELL	PR	07/01/2021	OW	123-37845	Razor 21A-2814B	EI
433921	WELL	PR	08/10/2017	OW	123-37847	Razor 21A-2815A	EI
433922	WELL	PR	07/01/2021	OW	123-37848	Razor 21A-2813A	EI
437408	WELL	PR	03/09/2015	OW	123-39527	Razor 21A-0913	EI
437409	WELL	PR	03/22/2015	OW	123-39528	Razor 21A-0914	EI
437411	WELL	PR	03/22/2015	OW	123-39530	Razor 21A-0915	EI
437414	WELL	PR	03/22/2015	OW	123-39533	Razor 21A-0916	EI

General Comment:

On April 11, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the Razor/21A Pad location (Location ID: 433919).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location				
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type				
Comment:	Entrance sign observed			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Tumbleweeds located among wellheads.			
Corrective Action:	Comply with Rule 606			Date: 04/30/2024
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment (pumping units) located on site.			
Corrective Action:	Comply with Rule 606			Date: 07/22/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	Hydrocarbons observed at multiple wellheads. See photo documentation.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Date:			Date: 04/23/2024
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 433917	Type: WELL	API Number: 123-37844	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433918	Type: WELL	API Number: 123-37845	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433921	Type: WELL	API Number: 123-37847	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 433922	Type: WELL	API Number: 123-37848	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437408	Type: WELL	API Number: 123-39527	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437409	Type: WELL	API Number: 123-39528	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437411	Type: WELL	API Number: 123-39530	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437414	Type: WELL	API Number: 123-39533	Status: PR	Insp. Status: EI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
709100275	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6519319