

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2024

Submitted Date:

04/22/2024

Document Number:

708903604

FIELD INSPECTION FORMLoc ID 335594 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

33 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arauz, Steven		steven.arauza@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281254	WELL	PR	11/14/2006	GW	045-11414	N.PARACHUTE EF 16D H29A 595	PR
281255	WELL	PR	02/01/2014	GW	045-11415	N.PARACHUTE EF 15B H29A 595	PR
281256	WELL	PR	11/10/2005	GW	045-11416	N.PARACHUTE EF01B H29A 595	PR
281257	WELL	PR	11/24/2006	GW	045-11417	N.PARACHUTE EF16B H29A 595	PR
281258	WELL	PR	11/03/2006	GW	045-11418	N.PARACHUTE EF09B H29A 595	PR
281259	WELL	PR	11/08/2006	GW	045-11419	N. PARACHUTE EF01D H29A 595	PR
281260	WELL	PR	11/10/2005	GW	045-11420	N.PARACHUTE EF 15D H29A 59	PR
281261	WELL	PR	02/01/2014	GW	045-11421	N.PARACHUTE EF 10D H29A 595	PR

General Comment:

CECMC Inspection Report Summary

On 04/22/2024 at approximately 14:01 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad.

Location # 335594 in Garfield County Colorado.

Please refer to inspection 708902896 conducted on 01/25/2024, previous corrective action has been completed.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 186 yards from East Fork Parachute Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained soils & gravel in multiple areas on location with a CA date of 04/29/2024
2. Housekeeping - Open hole/wildlife & personnel hazard with a CA date of 04/29/2024
3. Housekeeping - Multiple open ended piping on location/wildlife hazards with a CA date of 04/29/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Production separation equipment & tank battery located at Middlefork Station facility #'s 419757 & 470699

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open hole/wildlife & personnel hazard		
Corrective Action:	Comply with CECMC wildlife & safety rules	Date:	04/29/2024
Type	OTHER		
Comment:	Multiple open ended piping on location/wildlife hazards		
Corrective Action:	Comply with CECMC wildlife rules	Date:	04/29/2024
Type	OTHER		
Comment:	Stained soils & gravel in multiple areas on location		
Corrective Action:	Remove and properly dispose of all stained soils and gravel	Date:	04/29/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Gas lift meter houses - jersey barriers		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Jersey barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tanks - jersey barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sales meter houses - pipe rail fence & jersey barriers		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Sales		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	281254	Type:	WELL	API Number: 045-11414 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281255	Type:	WELL	API Number: 045-11415 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281256	Type:	WELL	API Number: 045-11416 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281257	Type:	WELL	API Number: 045-11417 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281258	Type:	WELL	API Number: 045-11418 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281259	Type:	WELL	API Number: 045-11419 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281260	Type:	WELL	API Number: 045-11420 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	281261	Type:	WELL	API Number: 045-11421 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift & gas lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	Producing, well on plunger lift & gas lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small areas of light compaction
				Material Handling And Spill Prevention		Chemical tank containments
Gravel						Sparse to none in small areas
		Compaction				
		Ditches				
Berms						
		Culverts				
		Gravel				Sparse to none

Comment: [Some fluid in chemical tank containment, may need maintenance in the near future.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping for observed compliance issues.	smelserw	04/22/2024
Production separation equipment & tank battery located at Middlefork Station facility #'s 419757 & 470699		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903605	Inspection 708903604 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520077
708903606	Inspection 708903604 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520078