

Inspection Photos

Loc: 484358

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 4/22/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road.



Inspection Photos



Photo 2. There are cuts installed for stormwater diversion however the loose soil berms need to be stabilized and tree debris must be removed. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 3. Facing east toward along the access road near the location. Topsoil was not salvaged along the road and is not very compacted.



Inspection Photos



Photo 4. Facing back west toward the flowline disturbance. It appears seeding was performed however loose soils are not stabilized. This area needs to be monitored and additional BMP's may need to be installed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 5. Facing east toward the wellsite. Topsoil was not salvaged along the road and is not very compacted.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 6. There is compressor engine installed b the wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 7. There is oily fluids in the engine skid that has spilled onto the ground. This must be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 8. There is stained soil outside fenced area that must be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 9. It appears there was a leak at the backside of the engine compressor.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 10. View of stained soil at the back side of the compressor about 6'x5'.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 11. There are fuel containers stored inside of secondary containment but have leaked. This needs to be cleaned up and netting needs to be installed over the top of this area to prevent wildlife entry.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos




Photo 12. It appears there is more stained soil at around the engine compressor.



Inspection Photos



Photo 13. North side of the location facing southwest. There are area where soils are very compacted. Seeding was performed in this area however vegetation will not grow well in compacted soils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 14. North side of the location are perimeter wattles. There are still red cutting by the wattles.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:484358 | Date: 4/22/2024

Inspection Photos



Photo 15. North side of the location facing west. Disturbed areas have been seeded. .

