

# Environmental Inspection

April 15, 2024

Operator: Woodbury Resources LLC

Location ID: 324766

API: 057-06483 Fuqua 19-02-10-H

Inspection Document #: 712100007

Jackson, CO

SWSE Section 18 T6N R78W

Alex Fischer

Environmental Supervisor - Western  
Colorado, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 1.** Entrance signage. NOTE: API shown is 05-057-06485, CORRECT API should read 05-057-06483.



## Inspection Photos

**Facility Name:** Fuqau 18-15 Pad

LocationID: 324766

**Apl: 057-06483, Fuqua 19-02-10-1H**

Date: April 15, 2024



**Photo 2.** Well signage. NOTE: API shown is 05-057-06485, CORRECT API should read 05-057-06483.



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources

Inspection Number: 712100007



Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 3.** Well is locked out.





Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 4.** Well is locked out.





**Photo 5.** Tank 00163 indicates signs of hydrocarbon staining.



Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 6.** Secondary containment liner compromised.






**Photo 7.** Secondary containment liner compromised with vegetation growth though liner.



Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 8.** Weeds/Debris near fire tube.





**Photo 9.** Weeds/Debris near fire tube.





**Photo 10.** Nest on catwalk.

Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 11.** Flare.







**Photo 12.** Looking east toward tank battery.

Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 13.** Weeds across location.





Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 14.** Trash/debris.





Inspection Photos  
Facility Name: Fuqau 18-15 Pad  
LocationID: 324766  
Apl: 057-06483, Fuqua 19-02-10-1H  
Date: April 15, 2024



**Photo 15.** Apparent gravel placed on hydrocarbon stained surface (See Inspection 690900189).





**Photo 16.** Apparent gravel placed on hydrocarbon stained surface (See Inspection 690900189).