

Catamount Energy Partners
Cox 2
Inspection 714000667 Remedial Report

Comment: Unused fencing and meter house equipment observed on location.

Corrective Action: **Comply with rule 606. Remove and properly store unused equipment.**

Action Taken: Removed fencing and meter house from location

Action Taken Date: 4/17/2024

Comment Cheatgrass observed along the southern edge of the disturbance.

Corrective Action **Comply with rule 1003.f**

Action Taken: Chemically treated weeds on location

Action Taken Date: 4/23/2024



Removed unused equipment



Removed unused equipment



- Chemically treated weeds