

# Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 320857

Inspection Document #: 714000707

Archuleta County, CO

Township: SESE 8 32N 5W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Seibel A1, A2  
Location ID: 320857



4/23/24  
+37.027596,-107.409479  
179° S



4/23/24  
+37.027077,-107.409092  
254° W

Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Seibel A1, A2  
Location ID: 320857

4/23/24  
+37.027517,-107.409581  
212° SW



**Photo 2.** Weedy debris corrective action identified in the previous inspection doc #693903984 has been addressed/resolved.

Inspection Photos  
Location Name: Seibel A1, A2  
Location ID: 320857



**Photo 3.** Weedy debris observed along the tank berm fence line and at both well heads.

Inspection Photos  
Location Name: Seibel A1, A2  
Location ID: 320857



**Photo 4.** Impacted surface material observed at the A1 well head.

Inspection Photos  
Location Name: Seibel A1, A2  
Location ID: 320857

4/23/24  
+37.027055,-107.409405  
292° W



**Photo 5.** View of southern interim reclamation area facing west. Vegetation comprised of crested wheatgrass and alfalfa.

Inspection Photos  
Location Name: Seibel A1, A2  
Location ID: 320857

4/23/24  
+37.021160,-107.407245  
281° W



**Photo 6.** Reference area comprised of crested and intermediate wheatgrass.