

Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 320869

Inspection Document #: 714000708

Archuleta County, CO

Township: SWNE 7 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Marquez A1
Location ID: 320869



4/23/24
+37.036269,-107.429940
182° S



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos

Location Name: Marquez A1

Location ID: 320869



Photo 2. Storm water corrective action identified in the previous inspection doc #693904254 has been addressed/resolved.

Inspection Photos

Location Name: Marquez A1

Location ID: 320869



Photo 3. Impacted surface material observed at the well head.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06165

Inspection Photos
Location Name: Marquez A1
Location ID: 320869

4/23/24
+37.035672,-107.430199
119° SE



Inspection Photos
Location Name: Marquez A1
Location ID: 320869

4/23/24
+37.035839,-107.430271
233° SW



Photo 5. Reference area comprised of smooth brome, rabbit brush and juniper.