

# Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 453717

Inspection Document #: 714000709

Archuleta County, CO

Township: Lot 2 7 32N 5W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Marquez A2, Luchini 32-6-12 2  
Location ID: 453717

4/23/24  
+37.032942,-107.440426  
61° NE



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos

Location Name: Marquez A2, Luchini 32-6-12 2

Location ID: 453717



**Photo 2.** Produced water sign/placard corrective action identified in the previous inspection doc #702500393 has been addressed/resolved.

Inspection Photos

Location Name: Marquez A2, Luchini 32-6-12 2

Location ID: 453717




**Photo 3.** View of weedy russian thistle debris piling up along the northern fence line and in the northeast corner of the disturbance.

Inspection Photos

Location Name: Marquez A2, Luchini 32-6-12 2

Location ID: 453717



**Photo 4.** Weedy russian thistle debris and impacted surface material observed at both well heads.

Inspection Photos

Location Name: Marquez A2, Luchini 32-6-12 2

Location ID: 453717



**Photo 5.** View of northern interim reclamation area facing north east. Vegetation comprised of intermediate and crested wheatgrass.



Inspection Photos

Location Name: Marquez A2, Luchini 32-6-12 2

Location ID: 453717



**Photo 6.** Reference area comprised of juniper and grazed grasses in the under story.