

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2024

Submitted Date:

04/18/2024

Document Number:

714200947

FIELD INSPECTION FORM

Loc ID 332754 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 19 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245865	WELL	TA	12/01/2023	GW	123-13660	ARISTOCRAT ANGUS 24-4	PA
271456	WELL	SI	12/01/2023	GW	123-22060	ARISTOCRAT ANGUS 3-6-4	SI
271457	WELL	PR	06/01/2022	OW	123-22061	ARISTOCRAT ANGUS 1-6-4	SI
424342	WELL	TA	12/01/2023	GW	123-33993	ARISTOCRAT ANGUS 4-6-4	PA
424349	WELL	SI	12/01/2023	GW	123-33996	ARISTOCRAT ANGUS 4-8-4	SI

General Comment:

[THIS IS A WELLHEAD/BATTERY INSPECTION.](#)

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	It appears contents/capacity is no longer legible on two tanks. See attached photos.		
Corrective Action:	Comply with Rule 605.h.	Date:	05/18/2024
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	One wellhead has incorrect signage. See attached photo.		
Corrective Action:	Comply with Rule 605.d.	Date:	05/18/2024

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	debris on various areas on location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/18/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused automation and gas meter house near seperators/ecds. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/18/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	6' chain link .		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6'chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares contianment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	UNKNOWN
Other (Capacity)	250 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shares containment with other tanks.
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		

Comment:	Centralized tank battery
Corrective Action:	Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 245865 Type: WELL API Number: 123-13660 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA; Form 6(S) in well file (in process)

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12
 Facility ID: 271456 Type: WELL API Number: 123-22060 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment: SI; it appears the valves are in a closed position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 01/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12
 Facility ID: 271457 Type: WELL API Number: 123-22061 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; it appears the valves are in a closed position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 12/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12
 Facility ID: 424342 Type: WELL API Number: 123-33993 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: SITE CONDITION

Comment: PA; Form 6(S) in well file (in process)

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12
 Facility ID: 424349 Type: WELL API Number: 123-33996 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; it appears valves are in a closed position.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary WEATHER CONDITIONS: cloudy, flurries On Thursday, April 18, 2024 at approximately 1000, I, Inspector Brittani Santistevan, conducted an on-site inspection at ARISTOCRAT ANGUS 4-8-4, 1-6-4, 3-6-4 (Crestone Peak Resources Operating, LLC), at location ID: 332754 in WELD COUNTY, Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Debris on various areas of location. Comply with Rule 606. (Corrective Action Date: May 18, 2024) See attached photo #11-16. 2. It appears the capacity/contents are no longer legible on one tank. Install sign to Comply with Rule 605.h. (Corrective Action Date: May 18, 2024) See attached photo #10. 3. It appears the contents are no longer legible on one tank. Install sign to Comply with Rule 605.h. (Corrective Action Date: May 18, 2024) See attached photo #9. 4. Unused automation and gas meter housing near ECDs/separators. Comply with Rule 606. (Corrective Action Date: May 18, 2024) See attached photo #14, 15. 5. It appears there is an incorrect wellhead sign at one well. Comply with Rule 605.d. (Corrective Action Date: May 18, 2024) See attached photo #1. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	04/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403761037	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515862
714200954	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515857