

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2024

Submitted Date:

04/18/2024

Document Number:

708201153**FIELD INSPECTION FORM**Loc ID 439471 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439471	LOCATION	AC			-	Coffelt 5-61-35_36 NWNW	RI
439473	WELL	PR	06/01/2021	OW	123-40451	Coffelt 5-61-35-0108BH2	RI

**General Comment:**[This is an Interim Reclamation and Stormwater Inspection for Location ID \(439471\).](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	Tumbleweed accumulations were observed throughout the location and within equipment. Refer to inspection photos for additional.		
Corrective Action:	Comply with Rule 606 to remove weed debris.	Date:	04/25/2024
Type	TRASH		
Comment:	Trash and debris observed throughout the location. Refer to attached inspection photos for additional.		
Corrective Action:	Comply with Rule 606 and remove all trash/debris from the location.	Date:	04/25/2024
Type	UNUSED EQUIPMENT		
Comment:	Old fence posts/h-brace located in the NE corner of the location remain from the initial location construction (e.g. before production equipment was moved to the south). Any fencing/posts that are not actively being used will need to be removed. Refer to attached inspection photos for additional.		
Corrective Action:	Comply with Rule 606 and remove any unused equipment.	Date:	04/25/2024
Type	OTHER		
Comment:	Stained soils were observed both inside and outside of secondary containment at tank battery and near equipment. Refer to attached inspection photos for additional.		
Corrective Action:	Properly dispose of oily waste in accordance with Rule 905.e.	Date:	05/03/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	439471	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	439473	Type:	WELL	API Number:	123-40451	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use: RANGELAND

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment

Corrective Action                      Date                     

1002b. SOIL REMOVAL AND  
SEGREGATION                     

Comment

Corrective Action                      Date                     

1002c. PROTECTION OF SOILS                     

Comment

Corrective Action                      Date                     

1002E. SURFACE DISTRURBANCE MINIMIZATION                     

Comment

Corrective Action                      Date                     

1003a. Waste and Debris removed?                     

Comment

Corrective Action                      Date                     

Unused or unneeded equipment onsite?                     

Comment

Corrective Action                      Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment

Corrective Action                      Date                     

Guy line anchors marked?                     

Comment

Corrective Action                      Date

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment This location does not comply with Rule 1003. It was observed that interim areas are not progressing towards vegetative standards. While some desirable vegetation was observed in the northern areas, there is evidence of russian thistle and kochia in the early growth stages throughout, and the southern portion of the interim areas consist mainly of russian thistle. Operator will need to perform active weed management and continue to monitor the site until it reaches Rule 1003 standards and regulations. Refer to attached inspection photos.

Corrective Action Comply with Rule 1003.Date 05/18/2024Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: 

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

No stormwater erosion issues observed at the location or along the access road.

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403760991	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515833">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515833</a>
708201168	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515824">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515824</a>