

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2024

Submitted Date:

04/18/2024

Document Number:

708201158**FIELD INSPECTION FORM**Loc ID 441005 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440999	WELL	SI	06/01/2023	OW	123-41214	Pronghorn D14-X44-28HNB	RI
441000	WELL	SI	06/01/2023	OW	123-41215	Pronghorn 14-44-28HNC	RI
441001	WELL	SI	06/01/2023	OW	123-41216	Pronghorn 13-43-28HNC	RI
441002	WELL	SI	06/01/2023	OW	123-41217	Pronghorn D-X-28HNC	RI
441003	WELL	SI	06/01/2023	OW	123-41218	Pronghorn C13-W43-28HNB	RI
441004	WELL	SI	06/01/2023	OW	123-41219	Pronghorn D13-X43-28HNB	RI
441005	LOCATION	AC			-	Pronghorn D-28 Pad	RI
441007	WELL	SI	06/01/2023	OW	123-41221	Pronghorn C-W-28HNC	RI

**General Comment:**[This is an Interim Reclamation and Stormwater Inspection for Location ID \(441005\).](#)

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	DEBRIS			
Comment:	Tumbleweed accumulations observed throughout the location and within equipment. Degraded straw wattles at SE sediment trap need to be removed as they are not intact. Refer to attached inspection photos.			
Corrective Action:	Comply with Rule 606 and remove all debris on location.			Date: 04/25/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities				
Facility ID: 440999	Type: WELL	API Number: 123-41214	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441000	Type: WELL	API Number: 123-41215	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441001	Type: WELL	API Number: 123-41216	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441002	Type: WELL	API Number: 123-41217	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441003	Type: WELL	API Number: 123-41218	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441004	Type: WELL	API Number: 123-41219	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441005	Type: LOCATION	API Number: -	Status: AC	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 441007	Type: WELL	API Number: 123-41221	Status: SI	Insp. Status: RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Environmental	
<b>Spill/Remediation:</b>	
Comment:	Remediation Project #33579 is still active and open. Continue to comply with 900 series rules.
Corrective Action:	<div></div> <div>Date: _____</div>
Emission Control Burner (ECB): _____	
Comment:	<div></div>
Pilot: _____	Wildlife Protection Devices (fired vessels): _____

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_



Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

No stormwater erosion issues observed at the location or along the access road.

Corrective Action:

Date:

**Pits:**

☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403760992	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515834">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515834</a>
708201170	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515826">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515826</a>