

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 320880

Inspection Document #: 714000723

Archuleta County, CO

Township: NWSE 7 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Quintana 32-5 7-2
Location ID: 320880

4/23/24
+37.029489,-107.433350
93° E



Photo 1. View of the disturbance taken from the access point facing center.



Inspection Photos
Location Name: Quintana 32-5 7-2
Location ID: 320880



Photo 2. Rutting observed on location, additional stabilization is needed to minimize site degradation.

Inspection Photos

Location Name: Quintana 32-5 7-2

Location ID: 320880



Photo 3. View of unaddressed erosion issues persisting in the western portion of the disturbance.

Inspection Photos

Location Name: Quintana 32-5 7-2

Location ID: 320880




Photo 4. Gully erosion and rutting erosion observed forming along the access road.

Inspection Photos

Location Name: Quintana 32-5 7-2

Location ID: 320880



Photo 5. Impacted surface material observed at the well head.



Inspection Photos
Location Name: Quintana 32-5 7-2
Location ID: 320880



4/23/24
+37.029254,-107.432965
39° NE

Photo 6. View of the northern interim reclamation area facing north east.
Vegetation comprised of smooth brome and rabbitbrush.

Inspection Photos
Location Name: Quintana 32-5 7-2
Location ID: 320880

4/23/24
+37.029626,-107.434513
215° SW



Photo 7. Reference area comprised of rabbitbrush, greasewood, sage brush and juniper.