

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2024

Submitted Date:

04/25/2024

Document Number:

708903621**FIELD INSPECTION FORM**Loc ID 334996 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297605	WELL	PR	09/01/2022	GW	045-16888	SAVAGE 20-16BB (PP20)	PR
297664	WELL	PR	09/01/2022	GW	045-16910	SAVAGE 20-9BB (PP20)	PR
297665	WELL	PR	09/01/2022	GW	045-16911	SAVAGE 20-16 (PP20)	PR
297666	WELL	PR	09/01/2022	GW	045-16912	SAVAGE 20-15(PP20)	PR
297667	WELL	PR	09/01/2022	GW	045-16913	SAVAGE 20-15BB (PP20)	PR

General Comment:**CECMC Inspection Report Summary**On 04/25/2024 at approximately 14:20 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at CAERUS PICEANCE LLC SAVAGE 20-16BB (PP20) Pad.

Location # 334996 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

Location is in close proximity to Rule 411a Surface Water External Buffer.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Failure to maintain chemical BMP with a CA date of 04/28/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLS	STEEL AST		,	
Comment:	Tanks equipped with telemetry					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities								
Facility ID:	297605	Type:	WELL	API Number: 045-16888	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	297664	Type:	WELL	API Number: 045-16910	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	297665	Type:	WELL	API Number: 045-16911	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	297666	Type:	WELL	API Number: 045-16912	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								
Facility ID:	297667	Type:	WELL	API Number: 045-16913	Status:	PR	Insp. Status:	PR
Producing Well								
Comment:	Producing, well on plunger lift							
Corrective Action:						Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12								

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Compaction				
Waddles						
		Gravel				Sparse to none in sections
		Culverts				
		Ditches				
Gravel						Sparse to none in areas
Compaction						Light compaction in areas
Berms						
Rip Rap						
				Material Handling And Spill Prevention		Failure to maintain chemical BMP

Comment: 1. Failure to maintain chemical BMP/chemical containment approximately 3/4 full of fluid/not sufficient to contain possible spill

Corrective Action: **Comply with CECMC Stormwater rules**

Date: 04/28/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Stormwater for observed compliance issue	smelserw	04/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903622	Inspection 708903621 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525271
708903623	Inspection 708903621 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525272