

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290



Photo # 4974 From entrance to location



Photo # 4975 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290



Photo # 4976 Location



Photo # 4977 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290



Photo # 4978 Location



Photo # 4979 Location



## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290



**Photo # 4980 Location**




**Photo # 4981 Unused equipment – ECD is disconnected & not in use**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290



**Photo # 4982 Unused equipment – ECD is disconnected & not in use**



**Photo # 4983 Multiple cellars lack wildlife egress**

## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290



Apr 25, 2024 at 11:32:29 AM



Apr 25, 2024 at 11:32:48 AM

**Photo # 4984 PRV & rupture disc vent lines terminate in an unsafe manner/do not comply with CECMC general safety rules & pressure safety device rules**

**Photo # 4985 PRV & rupture disc vent lines terminate in an unsafe manner/do not comply with CECMC general safety rules & pressure safety device rules**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 4-31 Pad

Location # 335290




Photo # 4986 Tank label lacks required information