

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 5051 From entrance to location



Photo # 5052 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 5053 Location



Photo # 5054 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 5055 Location



Photo # 5056 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 5057 PRV terminates in an unsafe manner/does not comply with CECMC general safety rules & pressure safety device rules



Photo # 5058 PRV terminates in an unsafe manner/does not comply with CECMC general safety rules & pressure safety device rules

Inspection Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 Pad

Location # 323980



Photo # 5059 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 5060 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules