

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2024

Submitted Date:

04/22/2024

Document Number:

708903604

**FIELD INSPECTION FORM**

Loc ID 335594 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 33 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281254	WELL	PR	11/14/2006	GW	045-11414	N.PARACHUTE EF 16D H29A 595	PR
281255	WELL	PR	02/01/2014	GW	045-11415	N.PARACHUTE EF 15B H29A 595	PR
281256	WELL	PR	11/10/2005	GW	045-11416	N.PARACHUTE EF01B H29A 595	PR
281257	WELL	PR	11/24/2006	GW	045-11417	N.PARACHUTE EF16B H29A 595	PR
281258	WELL	PR	11/03/2006	GW	045-11418	N.PARACHUTE EF09B H29A 595	PR
281259	WELL	PR	11/08/2006	GW	045-11419	N. PARACHUTE EF01D H29A 595	PR
281260	WELL	PR	11/10/2005	GW	045-11420	N.PARACHUTE EF 15D H29A 59	PR
281261	WELL	PR	02/01/2014	GW	045-11421	N.PARACHUTE EF 10D H29A 595	PR

**General Comment:**

CECMC Inspection Report Summary

On 04/22/2024 at approximately 14:01 hours, I, Compliance Specialist, Wayne Smelser  
Conducted a follow up inspection at CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad.  
Location # 335594 in Garfield County Colorado.

Please refer to inspection 708902896 conducted on 01/25/2024, previous corrective action has been completed.  
Location is within High Priority/Density/NSO/Black Bear Habitat areas.  
Location is approximately 186 yards from East Fork Parachute Creek.  
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained soils & gravel in multiple areas on location with a CA date of 04/29/2024
2. Housekeeping - Open hole/wildlife & personnel hazard with a CA date of 04/29/2024
3. Housekeeping - Multiple open ended piping on location/wildlife hazards with a CA date of 04/29/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Production separation equipment & tank battery located at Middlefork Station facility #'s 419757 & 470699

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soils & gravel in multiple areas on location		
Corrective Action:	Remove and properly dispose of all stained soils and gravel		Date: 04/29/2024
Type	OTHER		
Comment:	Open hole/wildlife & personnel hazard		
Corrective Action:	Comply with CECMC wildlife & safety rules		Date: 04/29/2024
Type	OTHER		
Comment:	Multiple open ended piping on location/wildlife hazards		
Corrective Action:	Comply with CECMC wildlife rules		Date: 04/29/2024

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	<a href="#">Chemical tanks - jersey barriers</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Jersey barriers</a>		
Corrective Action:		Date:	
Type	OTHER		
Comment:	<a href="#">Gas lift meter houses - jersey barriers</a>		
Corrective Action:		Date:	
Type	OTHER		
Comment:	<a href="#">Sales meter houses - pipe rail fence &amp; jersey barriers</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	<a href="#">Telemetry</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	<a href="#">Chemical tanks</a>		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	<a href="#">Taylor plugs located on all bradenhead. All bradenhead valves are accessible</a>		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	<a href="#">All wells on plunger lift</a>		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	<a href="#">Gas lift</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Thermoelectric generator</a>		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	<a href="#">Sales</a>		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	281254	Type:	WELL	API Number:	045-11414	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281255	Type:	WELL	API Number:	045-11415	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281256	Type:	WELL	API Number:	045-11416	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281257	Type:	WELL	API Number:	045-11417	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281258	Type:	WELL	API Number:	045-11418	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281259	Type:	WELL	API Number:	045-11419	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281260	Type:	WELL	API Number:	045-11420	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281261	Type:	WELL	API Number:	045-11421	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift & gas lift								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

**Producing Well**

Comment: Producing, well on plunger lift & gas lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small areas of light compaction
				Material Handling And Spill Prevention		Chemical tank containments
Berms						
		Gravel				Sparse to none
		Culverts				
		Ditches				
		Compaction				
Gravel						Sparse to none in small areas

Comment: Some fluid in chemical tank containment, may need maintenance in the near future.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Housekeeping for observed compliance issues.</a>	smelserw	04/22/2024
<a href="#">Production separation equipment &amp; tank battery located at Middlefork Station facility #'s 419757 &amp; 470699</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403764725	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520082</a>
708903605	Inspection 708903604 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520077">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520077</a>
708903606	Inspection 708903604 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520078">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520078</a>