

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/22/2024

Document Number:

709100268

FIELD INSPECTION FORMLoc ID 430061 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD State: CO Zip: 80111

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Parrish, Melissa		mparrish@fundareresources.com	
TRUITT, J CODY	281-513-0697	ctrutt@fundareresources.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430062	WELL	PR	06/01/2023	OW	123-36029	Razor 14-1143H	EI

General Comment:

On April 11, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the Razor 14-1143H pad location (Location ID: 430061).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Hydrocarbons observed from exhaust around pumping unit. See photo documentation.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	04/23/2024
Type	TRASH		
Comment:	Tumbleweeds observed within secondary containment.		
Corrective Action:	Comply with Rule 606	Date:	04/30/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (metal pipe, metal wheel, O-ring, pipe insulation, wood) located on site.		
Corrective Action:	Comply with Rule 606	Date:	04/30/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		
Other	Pump Jack			
Comment:	Hydrocarbons observed around a truck loadout. See photo documentation.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 05/22/2024

In Containment: No

Comment: ☒ Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:	Wildlife protections devices (netting) not adequate on secondary containment. See photo documentation.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 05/02/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

