

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/22/2024

Document Number:

709100270

FIELD INSPECTION FORM

Loc ID 312142 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218843	WELL	PR	03/22/1993	OW	075-05606	VAN GUNDY, FRED 2	EI

General Comment:

On April 11, 2024, ECMC Environmental Unit Staff Krystal Heibel inspected the VAN GUNDY, FRED-68N54W/35NWNE location (Location ID: 312142).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted on tanks		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/22/2024

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Hydrocarbon drips and drabs observed throughout the location.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	04/23/2024
Type	TRASH		
Comment:	Trash (aluminum cans, rope, wood, pipe) observed within pit.		
Corrective Action:	Comply with Rule 606	Date:	04/29/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	Hydrocarbon staining observed within the pit. Refer to photo documentation.			
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.			Date: 05/22/2024

In Containment: No

Comment: ☒ Multiple Spills and Releases?**Equipment:**

Type: Other	# 1		corrective date
Comment:	Active pit on location is not registered with ECMC.		
Corrective Action:	Operator shall provide a Form 15: Pit Report/Permit, including the pit coordinates. Operator shall submit the Form 27 with accurate coordinates for the pit.		
		Date:	05/22/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:		Burrowing observed on secondary containment.			
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 06/22/2024
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

