

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/29/2024

Document Number:

698601965

FIELD INSPECTION FORM

Loc ID 304784 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 274970 | WELL | PR | 02/20/2005 | GW | 125-08983 | BROWN 22-32 | PR |

General Comment:

Release discovered by inspector on Brown 22-32 well location while completing Follow-Up Inspections on wells in the area. The Brown Well sets just off the access two track and damp/muddy soil approximately 23' X 25' was noted emanating from the wellhead to the edge of access road. At the time of discovery no actual leak at wellhead was noted. Suspect the fluids are leaking around the packing when the Pump Jack is in operation. Pumping unit is not on continuous operation and is run by timer and the Pump Jack did not come on while inspector was on site for verification of packing leak. The Operator was notified of discovery 4/11/2024 2:30PM.

| Location | | | |
|--|--|----------|-------------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. | | |
| Corrective Action | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Well lease sign posted at access trail. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Well lease sign located at wellhead. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | Emergency contact information posted on well lease sign. | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Electric motor on the ground inside well fencing. | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| Produced Water | WELLHEAD | <= 1 bbl | |
| Comment: | Damp/muddy soil approximately 23' X 25' was noted emanating from the wellhead to the edge of access road. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. | | Date: <u>05/30/2024</u> |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock panel fencing around surface equipment at well location. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | Bradenhead plumbed to surface. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Digital Gas Meter Run. Meter Calibration/Test Log dated 6-22-23. Well Inlet Valve open. Gas Outlet Valve open. | | |

| | | | |
|---------------------------|---|-------|------------|
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Flowline mounted Meter Run Box. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric Motor. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | Dehydrator on gas meter run inlet. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Pump Jack Power and Control Panel. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Rods and tubing in the wellbore. Tubing valve open. Casing valve open. Well appears to be releasing fluid at the packing. | | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 603.c.(12). | Date: | 04/12/2024 |

Venting:

| | | | |
|--------------------|----------------------------|-------|--|
| Yes/No | YES | | |
| Comment: | Fluid release at wellhead. | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 274970 Type: WELL API Number: 125-08983 Status: PR Insp. Status: PR

Producing Well

Comment: Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.
Electronic Well File reflects last Production/Status reported 2/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 698601994 | Inspection photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528931 |