

Inspection Photos
Location Name: TEP Rocky Mountain LLC DEVER A Pad
Location # 311676



Photo # 5227 From entrance to location



Photo # 5228 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC DEVER A Pad

Location # 311676



Photo # 5229 Location



Photo # 5230 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC DEVER A Pad

Location # 311676



Photo # 5231 Location



Photo # 5232 Location

Inspection Photos
Location Name: TEP Rocky Mountain LLC DEVER A Pad
Location # 311676



Photo # 5233 Location



Photo # 5234 Debris



Inspection Photos

Location Name: TEP Rocky Mountain LLC DEVER A Pad

Location # 311676



Photo # 5235 Cellar not properly covered/wildlife & personnel hazard



Photo # 5236 Cellar not properly covered/wildlife & personnel hazard

Inspection Photos

Location Name: TEP Rocky Mountain LLC DEVER A Pad

Location # 311676



Photo # 5237 Possible wellhead leak/gas bubbling up around wellhead through water in cellar



Photo # 5238 Possible wellhead leak/gas bubbling up around wellhead through water in cellar

Inspection Photos

Location Name: TEP Rocky Mountain LLC DEVER A Pad

Location # 311676



Photo # 5239 Possible wellhead leak/gas bubbling up around wellhead through water in cellar




Photo # 5240 Debris

Inspection Photos
Location Name: TEP Rocky Mountain LLC DEVER A Pad
Location # 311676



Photo # 5241 PRV vent line terminates in an unsafe manner /does not comply with CECMC pressure safety device rules & general safety rules



Photo # 5242 PRV vent line terminates in an unsafe manner /does not comply with CECMC pressure safety device rules & general safety rules

Inspection Photos
Location Name: TEP Rocky Mountain LLC DEVER A Pad
Location # 311676



Photo # 5243 Hole in liner/liner needs maintenance



Photo # 5244 Hole in liner/liner needs maintenance