



Wellhead Closure Checklist 2

Additional Attachments (Optional)	Flowline Closure
Site Name	Canepa 6-21
Remediation Project #	31886
Wellhead Information	
Weather	49° overcast
Client	Oxy
Location	
Latitude	40.26091
Longitude	-104.93467
General Condition of Site	Good
USCS Soil Type	Clay Loam / Clay Loam
Estimated Depth to Groundwater	<20'
Hydrocarbon Impacted Soils / Spills	None observed
Salt Crusted Soils or Impacted Vegetation	None observed

Soil Samples

#	Sample Date	Sample Time	Soil Sample ID	PID Readings	Visual	Olfactory	Equipment Name
R1	01/24/2024	12:40 PM	FL-B01@4'	0.7	N.S	N.O	Flowline at Separator
R2	01/24/2024	12:50 PM	FL-B02@4'	0.8	N.S	N.O	Flowline
R3	01/24/2024	01:10 PM	FL-B03@4'	0.4	N.S	N.O	Flowline
R4	01/24/2024	01:30 PM	FL-B04@4'	0.7	N.S	N.O	Flowline Directional Change
R5	01/25/2024	02:00 PM	WH-B01@6'	0.9	N.S	N.O	Wellhead
R6	01/25/2024	02:01 PM	WH-N01@5'	1.1	N.S	N.O	Wellhead
R7	01/25/2024	02:02 PM	WH-S01@5'	1.3	N.S	N.O	Wellhead
R8	01/25/2024	02:03 PM	WH-E01@5'	1.0	N.S	N.O	Wellhead
R9	01/25/2024	02:04 PM	WH-W01@5'	0.9	N.S	N.O	Wellhead
R10	01/25/2024	02:05 PM	WHS-N01@3"	0.8	N.S	N.O	Wellhead Surface
R11	01/25/2024	02:06 PM	WHS-S01@3"	0.9	N.S	N.O	Wellhead Surface
R12	01/25/2024	02:07 PM	WHS-E01@3"	1.2	N.S	N.O	Wellhead Surface
R13	01/25/2024	02:08 PM	WHS-W01@3"	0.7	N.S	N.O	Wellhead Surface
R14	01/25/2024	02:10 PM	FL-B05@4'	0.8	N.S	N.O	Flowline at Wellhead
R15	01/25/2024	02:12 PM	WH-BG01@3'	0.6	N.S	N.O	Wellhead Background
R16	01/25/2024	02:14 PM	WH-BG01@6'	0.6	N.S	N.O	Wellhead Background
R17	01/25/2024	02:16 PM	WH-BG02@3'	0.4	N.S	N.O	Wellhead Background
R18	01/25/2024	02:18 PM	WH-BG02@6'	0.5	N.S	N.O	Wellhead Background
R19	01/25/2024	02:20 PM	WH-BG03@3'	0.6	N.S	N.O	Wellhead Background

#	Sample Date	Sample Time	Soil Sample ID	PID Readings	Visual	Olfactory	Equipment Name
R20	01/25/2024	02:22 PM	WH-BG03@6'	0.5	N.S	N.O	Wellhead Background
R21	01/29/2024	01:10 PM	FL-B06@4'	0.8	N.S	N.O	Flowline
R22	01/29/2024	01:12 PM	FL-B07@4'	0.3	N.S	N.O	Flowline
R23	01/29/2024	01:16 PM	FL-B08@4'	1.4	N.S	N.O	Flowline
R24	01/29/2024	01:20 PM	FL-B09@4'	0.6	N.S	N.O	Flowline
R25	01/29/2024	01:23 PM	FL-B10@4'	0.1	N.S	N.O	Flowline
R26	01/29/2024	01:58 PM	FL-B11@4'	1.1	N.S	N.O	Flowline

Photo(s)

R1 - P1



Looking east

R2 - P1



Looking west

R3 - P1




Looking west

R4 - P1



Looking west

R5 - P1



Looking north

R7 - P1



Looking south

R8 - P1



Looking east

R9 - P1



Looking west

R15 - P1



Looking north

R17 - P1




Looking south

R19 - P1



Looking west

R21 - P1




facing south

R22 - P1



R23 - P1



facing south

R24 - P1




R25 - P1



facing south

R26 - P1



Other observations regarding wellheads

Summary

Was impacted soil identified?	No
Total number of soil samples field screened	26
Total number of soil samples collected	26
Highest PID Reading	1.3
Total number of soil samples submitted to lab for analysis	10
Was groundwater encountered during the investigation?	No
Measured depth to groundwater	
Was remedial groundwater removal conducted?	
Date Groundwater was encountered	
Commencement date of removal	
Sheen on groundwater?	
Free product observed?	
Volume of groundwater removed prior to sampling	
Volume of groundwater removed post sampling	
Total volume of groundwater removed	
Total number of groundwater samples collected	
Total number of groundwater samples submitted to lab for analysis	