

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (01EB) Pad

Location ID: 416887



Photo # 5437 From entrance to location



Photo # 5438 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (01EB) Pad

Location ID: 416887



Photo # 5439 Location



Photo # 5440 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (01EB) Pad

Location ID: 416887



**Photo # 5441 Tank is partially open & available for entry by wildlife/wildlife hazard**



**Photo # 5442 Earthen secondary containment damaged /does not comply with CECMC secondary containment rules**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (01EB) Pad

Location ID: 416887




Photo # 5443 Wellhead sign lacks required info



Photo # 5444 Wellhead sign lacks required info

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (01EB) Pad

Location ID: 416887



Photo # 5445 Wellhead sign lacks required info



Photo # 5446 Wellhead sign lacks required info

## Inspection Photos

Location Name: CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (01EB) Pad

Location ID: 416887



Photo # 5447 Debris