

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/17/2024

Submitted Date:

04/25/2024

Document Number:

697602346

FIELD INSPECTION FORM

Loc ID 328358 Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485891	SPILL OR RELEASE	CL	01/18/2024		-	Wardell H 19-2J Flowline	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 485891. Any corrective actions from previous inspections that have not been addressed are still applicable.

Operator and environmental personnel were on location to remove remaining impacts in soil.

Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:					
Type	Area	Volume			
OTHER					
Comment:	Fencing around the excavation is adequate.				
Corrective Action:					Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date: _____

Inspected Facilities

Facility ID: 485891 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	Oily waste is being stockpiled on location.			
Corrective Action	Operator shall properly dispose of oily waste in accordance with Rule 905.e. Additionally, Operator shall manage waste in compliance with Rule 913.b. (5)B and ECMC Guidance 913.b.(5)B i-v.			Date: 05/02/2024

Spill/Remediation:

Comment:	Operator and environmental personnel were on site removing impacted soil from the remedial excavation. Staining was observed within the excavation,		
Corrective Action:	Operator shall submit a Form 27 for Spill ID 485891 that includes a specific workplan and timeline to address the remaining impacts. No Form 27 has been submitted at the time of this inspection.		Date: 04/18/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403770252	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525037
697602347	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6525025