

Inspection Photos

API: 017-07523

Operator: ANADARKO E&P ONSHORE LLC

Inspection Date: 4/1/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The cattleguard has not been removed..



Inspection Photos



Photo 2. Facing east along the access road. The road was never recontoured. Native vegetation has re-established along the road.



Inspection Photos



Photo 3. Facing east along the access road. The road was never recontoured.



Inspection Photos



Photo 4. Facing north at the location. The perennial vegetation has fully established throughout the location.



Inspection Photos



Photo 5. Facing south at the location. The perennial vegetation has fully established throughout the location.



Inspection Photos



Photo 6. Facing east at the location. There are berms that remain at the location where tank battery was located..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07523 | Date: 4/1/2024