

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2024

Submitted Date:

05/02/2024

Document Number:

694100349**FIELD INSPECTION FORM**Loc ID 329853 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, PDC		cogccinspection@pdce.com	All Inspections
,		cogccinspection@pdce.com	All Inspections
,		cogccinspection@pdce.com	All inspections

General Comment:

This is an environmental inspection for Location 329853 Sanford Location. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

This inspection was in response to a recent spill. This spill has been reported to ECMC and clean up and remediation are ongoing.

☐ Multiple Spills and Releases?**Fencing/:**

Type

Comment:

Orange construction fencing around the spill location has blown down. Multiple sections need to be reattached.

Corrective Action:

Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/09/2024

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	Perimeter berm at SE corner of pad near meter house and aboveground pipeline risers has been damaged by a vehicle tire. Rut needs to be filled and re-compacted.					
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).					Date: 05/16/2024

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type	
Comment:	

Location ID: 329853 CDP: _____

Comment:

Corrective Action: **Date:** _____

<u>Comment:</u>		
Corrective Action:		Date:

Comment:
Corrective Action: **Date:**

Date: 05/16/2024

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

Name: _____ Phone Number: _____ Agreed to Attend: _____

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

This inspection was in response to a recent spill. This spill has been reported to ECMC and clean up and remediation activities are ongoing.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :

LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100350	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534084