

# Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 5647 From entrance to location



Photo # 5648 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 5649 Location



Photo # 5650 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 5651 Location

Photo # 5652 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



Photo # 5653 Location



Photo # 5654 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



**Photo # 8080 From inspection 708903187 conducted on 03/01/2024 Valve on production tank leaking fluid**

**Photo # 5655 Valve on production tank leaking fluid**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



**Photo # 8081 From inspection 708903187 conducted on 03/01/2024 Valve on production tank leaking fluid**



**Photo # 5656 Valve on production tank leaking fluid**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Warren 15-9 (PI15) Pad

Location #: 334751



**Photo # 5657 Valve on production tank leaking fluid**

**Photo # 5658 Valve on production tank leaking fluid**