



FORM
INSP

Rev
X/20

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/03/2024
Submitted Date:
05/03/2024
Document Number:
707602665

Loc ID
323714

Inspector Name:
Evins, Bret

On-Site Inspection ☐
2A Doc Num:

Operator Information:
ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:
☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:
15 Number of Comments
0 Number of Corrective Actions
☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245611	WELL	TA	12/19/2019	OW	123-13406	TREBOR B12-7	TA

General Comment:
This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.416800 / -104.498219

Abandoned Centralized Battery formerly served 3 Location IDs
(323714, 323705, 323772).
(Well(s): 1: Temporarily Abandoned | TA ; 2: Plugged & Abandoned | PA).

Reference (Associated Well(s), Battery Inspections):
*Follow-up to Field Inspection Report doc. #707602622, dated: 04/29/2024.
**FIRR Reference: doc# 403778709, dated: 05/03/2024.

Date Run: 5/4/2024 Doc [#707602665]

Page 1 of 6

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Prior Corrective Action(s) Resolved. Refer to CECMC Synopsis on this report.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Emission Control Device			# 0	corrective date
Comment:	Battery Abandoned. Equipment removed.			
Corrective Action:				Date:
Type: Gas Meter Run			# 0	
Comment:	Battery Abandoned. Equipment removed.			
Corrective Action:				Date:
Type: Horizontal Heated Separator			# 0	
Comment:	Battery Abandoned. Equipment removed.			
Corrective Action:				Date:
Type: Bradenhead			# 1	

Comment: Appears plumbed to surface.		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 0	
Comment: Temporarily Abandoned TA. Equipment removed.		Date:
Corrective Action:		Date:
Type: Other	# 1	
Comment: Wellhead: w/ Master, casing valves.		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment: Battery Abandoned. Equipment removed.					Date:
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:				Date:	
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment: Battery Abandoned. Equipment removed.					Date:
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 245611 Type: WELL API Number: 123-13406 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-out, Tagged-out | LOTO.
Black NEWS tag posted.
CECMC records last prod: 03/2017.

Form 4 on file. TA date: 10/03/2019. Approved.
DH-CIBP set.
Form 6A on file. Out-of-Svc Designation.
Date: 03/01/2017. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/30/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 05/03/2024 at approximately 15:52 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: TREBOR-65N64W/12SWNE Location ID: 323714 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.416800 / -104.498219</p> <p>During this inspection, the following prior possible compliance issue(s) appear to be addressed: 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 05/15/2024. (14-days). See photo #2. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>**Overgrown Vegetation at wellsite NOW Mitigated. as of 05/03/2024. See photo(s) #2, 3. Corrective Action(s), NOW resolved. CECMC photo(s) provided for verification. Operator photo(s) attached to FIRR doc# 403778709, dated: 05/03/2024, for verification.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/03/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602666	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6535674