

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403236058

Date Received:

11/21/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 702500769

Inspection Date: 11/10/2022

FIR Submit Date: 11/10/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306921

Location Name: WARREN DAVIS GAS UNIT Number: 13NWSW County: LA PLATA
C-N33N9W

Qtrqtr: NWS Sec: 13 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.101333 Longitude: -107.783098

FACILITY - API Number: 05-067-00 Facility ID: 277999

Facility Name: WARREN DAVIS C Number: 2

Qtrqtr: NWS Sec: 13 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.101333 Longitude: -107.783098

CORRECTIVE ACTIONS:

1 CA# 166053

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 11/25/2022

Response: CA COMPLETED

Date of Completion: 11/12/2022

Operator Comment: On site production technician verified drip is water condensation, not produced water, from the active burner tube and weather temperature changes. Since there is not a production release, there is no impacted material to remove.

ECMC Decision: _____

ECMC
Representative:

2 CA# 166054

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 11/11/2022

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Response: CA COMPLETED

Date of Completion: 11/12/2022

Operator
Comment: On site production technician verified drip is water condensation, not produced water, from an active burner tube and weather temperature changes. There is no production spill or release to contain or clean nor equipment to tighten.

ECMC Decision: _____

ECMC
Representative:

3 CA# 166055

Corrective Action: All unused equipment must be returned to use or stored off location per rule 606.

Date: 11/18/2022

Response: CA COMPLETED

Date of Completion: 11/12/2022

Operator
Comment: Identified equipment (can) has been removed. See the attached photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Katherine Feir

Signed: _____

Title: Compliance Coordinator

Date: 11/21/2022 12:59:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403236058	FIR RESOLUTION SUBMITTED
403236066	completion photo, equipment removed

Total Attach: 2 Files