

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
402652951

Date Received:
04/08/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria</u>	<u>Dizghinjili</u>	<u>vdizghinjili@kpk.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 690102357
Inspection Date: 04/01/2021 FIR Submit Date: 04/06/2021 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333225

Location Name: CAMENISCH-61N67W Number: 2SWSW County: WELD
Qtrqtr: SWS Sec: 2 Twp: 1N Range: 67W Meridian: 6
W
Latitude: 40.074750 Longitude: -104.865280

FACILITY - API Number: 05-123- -00 Facility ID: 239679

Facility Name: CAMENISCH Number: 1
Qtrqtr: SWS Sec: 2 Twp: 1N Range: 67W Meridian: 6
W
Latitude: 40.074750 Longitude: -104.865280

CORRECTIVE ACTIONS:

1 CA# 148122

Corrective Action:

Date: 05/07/2021

Provide information requested below to COGCC Integrity Inspector (via email) and add to Corrective Actions section of COGCC supplemental form 19 spill report (pertaining to compliance of COGCC series 1100 flowline regulations):

- 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/ operator determination)
- 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control)
- 3) Description of flowline repair/replacement work completed (1102.j. Repair)
- 4) Perform flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning well to service (1102.j.4 and 1102.O). Contact COGCC Integrity Inspector with schedule of repair work and pressure testing. Upload flowline pressure testing chart/ data to COGCC Form 19 subsequent.
- 5) Ensure OOSLAT (valves tagged out) in place to prevent unintentional release per 1102.j.7 (prior to and during time of repair).

Response: CA COMPLETED

Date of Completion: 04/08/2021

Operator
Comment:

Form 19-S Doc #402652607 has been submitted to COGCC 04-08-2021.

ECMC Decision: **Not Approved**

ECMC
Representative:

Corrective Actions not completed; no communication with COGCC Inspector

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed: _____

Title: Regulatory Technician

Date: 4/8/2021 12:48:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402652951	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files