

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402821161

Date Received:

09/23/2021

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-1832

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Moore, Todd

(214) 244-3819

kiowagas@sbcglobal.net

. Engineering

dnr\_cogccengineering@state.co.us

Leonard, Mike

mike.leonard@state.co.us

Mercer, Lauren

lauren.mercer@coag.gov

Hughes, Jim

jimo.hughes@state.co.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 700300157

Inspection Date: 06/02/2021

FIR Submit Date: 06/04/2021

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: ALAMOSA DRILLING INC

Company Number: 900

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-1832

### LOCATION - Location ID: 320851

Location Name: NIELSEN-N32N1E Number: 18NWNE County: ARCHULETA

Qtrqtr: NWNE Sec: 18 Twp: 32N Range: 1E Meridian: N

Latitude: 37.016317 Longitude: -106.882283

### FACILITY - API Number: 05-007- -00 Facility ID: 205238

Facility Name: NIELSEN Number: 3

Qtrqtr: NWNE Sec: 18 Twp: 32N Range: 1E Meridian: N

Latitude: 37.016317 Longitude: -106.882283

### CORRECTIVE ACTIONS:

1 CA# 151709

Corrective Action: Demonstrate how design of containment structure is "another engineer equivalent" per Rule 421.b.(3)

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 09/07/2021

Operator Comment: Re-designed to become a part of the existing containment facility and function similar to a retaining wall. Reconstruction to begin next month. Also confirming the actual base flood plane elevation.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 151710

Corrective Action: Inspect and maintain tank per Rule 609.b

Date: 09/21/2020

Response: CA COMPLETED

Date of Completion: 09/08/2021

Operator Comment: Inspected and ordered materials for maintenance to begin September 28.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 151711

Corrective Action: Immediately Stop venting at wellhead without approved sundry notice whether through open valves or poorly maintained valves and fittings.

Date: 06/16/2020

Response: CA COMPLETED

Date of Completion: 07/08/2021

Operator Comment: Corrected July 8.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**4** CA# 151712

Corrective Action: Install emergency services number (911 if available or local dispatch if not)

Date: 07/05/2021

Response: CA COMPLETED

Date of Completion: 09/28/2021

Operator Comment: Additional information was completed by local Sign company July 27 and installed July 28.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**5** CA# 151713

Corrective Action: stop venting without approval, repair thief hatch seal

Date: 06/03/2021

Response: CA COMPLETED

Date of Completion: 07/08/2021

Operator Comment: Corrected July 8.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Venting from the wellhead and tank was corrected July 8. Well shuts in at 4 psig.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Todd Moore

Signed: \_\_\_\_\_

Title: President

Date: 9/23/2021 3:36:22 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402821161	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files