

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403741997

Date Received:

04/03/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205651

Inspection Date: 03/06/2024

FIR Submit Date: 03/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335742

Location Name: CLOUGH-66S94W Number: 16NENW County: _____

Qtrqtr: NENW Sec: 16 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.530709 Longitude: -107.896350

FACILITY - API Number: 05-045- -00 Facility ID: 335742

Facility Name: CLOUGH-66S94W Number: 16NENW

Qtrqtr: NENW Sec: 16 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.530709 Longitude: -107.896350

CORRECTIVE ACTIONS:

1 CA# 192784

Corrective Action: Maintain fence at wellheads.

Date: 03/14/2024

Response: CA COMPLETED

Date of Completion: 03/12/2024

Operator Comment: Fence has been repaired. Corrective action completed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 192785

Corrective Action: Comply with 606 Rules.

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 04/11/2024

Operator Comment: The pipe that is referred to in the inspection report is irrigation pipe that belongs to the land owner. TEP agrees that the pipe is in dis-repair; however, it is not TEP's responsibility or obligation to remove pipe that was intentionally installed by the land owner for specific irrigation purposes.

ECMC Decision:

ECMC
Representative:

3 CA# 192786

Corrective Action: Comply with 1003 Rules and conduct interim reclamation on areas not reasonably needed for production.

Date: 04/30/2024

Response: CA COMPLETED

Date of Completion: 04/03/2024

Operator Comment: The flowlines from the existing, producing gas wells run through the middle of the area that the inspector is requesting to be reclaimed (see attached diagram). The flowlines between the well heads and separators are buried approximately 4-foot deep and also run through the fill slope just north of the separators. Reclaiming portions of the area over the existing flowlines would reduce the amount of cover over the flowlines and could result in operational and safety issues. This area is still reasonably needed for existing production needs and TEP will reclaim the entire area at the time of final reclamation.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed or addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Environmental Lead

Date: 4/3/2024 5:12:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403741997	FIR RESOLUTION SUBMITTED
403742107	Diagram showing area still needed for existing production needs

Total Attach: 2 Files