

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/25/2024

Submitted Date:

04/28/2024

Document Number:

708903649

**FIELD INSPECTION FORM**

Loc ID: 323980 Inspector Name: Smelser, Wayne On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 20 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211400	WELL	PR	06/12/1997	GW	045-07160	GIBSON GULCH UNIT 15-30	PR

**General Comment:**  
 CECMC Inspection Report Summary  
 On 04/25/2024 at approximately 12:24 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 15-30 Pad. Location # 323980 in Garfield County Colorado.  
 Location is within High Priority/Density/NSO/Black Bear Habitat areas. While there, I observed normal production operations.  
 During this inspection the following compliance issues were observed:  
 1. Equipment - PRV, PRV vent line & rupture disc vent line do not comply with CECMC rules with a CA date of 05/05/2024  
 2. Stormwater - Culvert/BMP needs maintenance with a CA date of 05/13/2024  
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection report  
 Remote location/split pad - Shared facilities with the GIBSON GULCH UNIT 15-30 D pad, location # 324014

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at intersection of CR 311 & lease road		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Small amount of stained soils & gravel near wellhead		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels & cattle panels		
Corrective Action:			Date:

Type	TANK BATTERY		
Comment:	Hog panels & barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels & cattle panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	1 PRV vent line terminates in an unsafe manner/does not comply with CECMC general safety rules & pressure safety device rules  1 PRV vent line & 1 rupture disc vent line do not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC general safety rules & pressure safety device rules		Date: 05/05/2024
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Tank is not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 211400 Type: WELL API Number: 045-07160 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			Culvert needs maintenance
Gravel						Sparse to none in some areas
		Gravel				Sparse to none
Compaction						Small areas of light compaction
		Ditches				
		Compaction				Light compaction in some sections

Comment: [1. Culvert needs maintenance \(on lease road at entrance to location on N/NE side of location\)](#)

Corrective Action: [Comply with CECMC Stormwater rules](#)

Date: 05/13/2024

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment &amp; Stormwater for observed compliance issues.</a>	smelserw	04/28/2024
<a href="#">Remote location/split pad - Shared facilities with the GIBSON GULCH UNIT 15-30 D pad, location # 324014</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403771759	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527263">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527263</a>
708903650	Inspection 708903649 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527261">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527261</a>
708903651	Inspection 708903649 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527262">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527262</a>