

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2024

Submitted Date:

04/29/2024

Document Number:

698601955

FIELD INSPECTION FORM

Loc ID 304856 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275557	WELL	PR	03/01/2022	GW	125-09070	ROCKWELL 34-7	PR

General Comment:

Inspector is completing Follow-up inspection as required by FIR. Follow-up inspection will ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 01/31/2024 FIR document number 698601608.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well sign at well location shows Foundation Energy as Operator.		
Corrective Action:	Install sign to comply with Rule 605.a	Date:	04/03/2024
	Corrective action date remains the same to document period of non-compliance.		

Emergency Contact Number:

Comment:	Emergency contact information posted on well sign at wellhead and CR/access intersection is incorrect. 866-767-3600 is Foundation Energy.	
Corrective Action:	Install sign to comply with Rule 605.a	Date: 04/03/2024
	Corrective action date remains the same to document period of non-compliance.	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 275557 Type: WELL API Number: 125-09070 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403773175	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528729
698601985	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6528666