

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2024

Submitted Date:

04/29/2024

Document Number:

708302088**FIELD INSPECTION FORM**

Loc ID 335482	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	------------------------------------	---	-------------------

Operator Information:

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299170	WELL	PR	01/01/2011	GW	045-17584	SHELL 697-34-14B	PR
299171	WELL	PR	07/19/2010	GW	045-17585	SHELL 697-34-14A	PR
299172	WELL	PR	07/19/2010	GW	045-17586	SHELL 697-34-22A	PR
299173	WELL	PR	07/01/2011	GW	045-17587	SHELL 697-34-22B	PR
299894	WELL	PR	01/18/2011	GW	045-17764	SHELL 697-34-08A	PR
299895	WELL	PR	04/10/2010	GW	045-17765	SHELL 797-03-06A	PR
299896	WELL	PR	05/23/2011	GW	045-17766	SHELL 797-03-06B	PR
299897	WELL	PR	07/01/2011	GW	045-17767	SHELL 697-34-08B	PR
300292	WELL	PR	04/28/2011	GW	045-17878	SHELL 797-03-15A	PR
300293	WELL	PR	02/21/2012	GW	045-17879	SHELL 697-34-16A	PR
300303	WELL	PR	07/21/2011	GW	045-17882	SHELL 797-03-15B	PR
300304	WELL	PR	06/27/2011	GW	045-17883	SHELL 797-03-31A	PR
300305	WELL	PR	06/27/2011	GW	045-17884	SHELL 697-34-16B	PR
300306	WELL	PR	04/28/2011	GW	045-17885	SHELL 797-03-39B	PR
300307	WELL	PR	07/21/2011	GW	045-17886	SHELL 797-03-39A	PR
300308	WELL	PR	04/28/2011	GW	045-17887	SHELL 797-03-38	PR
300309	WELL	PR	04/28/2011	GW	045-17888	SHELL 797-03-37	PR
300310	WELL	PR	06/27/2011	GW	045-17889	SHELL 797-03-31B	PR
300311	WELL	PR	06/27/2011	GW	045-17890	SHELL 797-03-23A	PR
300312	WELL	PR	06/27/2011	GW	045-17891	SHELL 797-03-23B	PR
374710	WELL	PR	06/27/2011	GW	045-18386	SHELL 697-34-24	PR

General Comment:

COGCC Inspection Report Summary

On 4/23/2024 at approximately 13:40, Compliance Inspector Matthew Morris conducted an on-site inspection at LARAMIE ENERGY LLC, Shell/0797-03B Pad at Location ID #335482 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Debris in secondary containment

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Delay in report submission due to technical issues. Any corrective action dates will be in effect from date of submission, not date of inspection.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/1-800-891-6191

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris in secondary containment.		
Corrective Action:	Remove debris to comply with Rule 606.	Date:	05/06/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Pipe rails		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Gas Meter Run	# 20				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 20				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 20				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 20				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 15				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 15				
Comment:					
Corrective Action:				Date:	
Type: Dehydrator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 20				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID:	299170	Type:	WELL	API Number: 045-17584 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299171	Type:	WELL	API Number: 045-17585 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299172	Type:	WELL	API Number: 045-17586 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299173	Type:	WELL	API Number: 045-17587 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299894	Type:	WELL	API Number: 045-17764 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299895	Type:	WELL	API Number: 045-17765 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299896	Type:	WELL	API Number: 045-17766 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	299897	Type:	WELL	API Number: 045-17767 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300292	Type:	WELL	API Number: 045-17878 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300293	Type:	WELL	API Number: 045-17879 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300303	Type:	WELL	API Number: 045-17882 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300304	Type:	WELL	API Number: 045-17883 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300305	Type:	WELL	API Number: 045-17884 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300306	Type:	WELL	API Number: 045-17885 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:			Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	300307	Type:	WELL	API Number: 045-17886 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	300308	Type:	WELL	API Number:	045-17887	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	300309	Type:	WELL	API Number:	045-17888	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	300310	Type:	WELL	API Number:	045-17889	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	300311	Type:	WELL	API Number:	045-17890	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	300312	Type:	WELL	API Number:	045-17891	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	374710	Type:	WELL	API Number:	045-18386	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well									
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel						
		Compaction				
		Gravel				
Sediment Traps						
		Culverts				
Ditches						
		Ditches				
Compaction						
		Sediment Traps				
		Check Dams				

Comment: Light gravel and compaction on location and lease road; future stormwater events may create tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403772359	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527907
708302089	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6527901