

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2024

Submitted Date:

04/30/2024

Document Number:

699700358

FIELD INSPECTION FORM

Loc ID 322391 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Arnim, Rees	(713) 469-0275	rarnim@locin.energy	
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111790	PIT				-	LEWIS USA 25-15	EI
111791	PIT				-	LEWIS USA 25-15	EI
210400	WELL	SI	10/01/2023	GW	045-06156	LEWIS USA 25-15	EI
467552	SPILL OR RELEASE	CL	06/16/2022		-	SPILL/RELEASE POINT	EI

General Comment:

4/29/2024 ECMC Environmental Inspection.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Information inaccurate on tank.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/30/2024

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:

Type	OTHER		
Comment:	Mangled wellhead cover within tank battery secondary containment structure.		
Corrective Action:	Comply with Rule 606.	Date:	05/07/2024
Type	OTHER		
Comment:	Landslide within tank battery secondary containment structure.		
Corrective Action:	Comply with Rule 602 and maintain all Oil and Gas Facilities in a safe manner. Operator shall compltw with Rule 1002.f.	Date:	05/30/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 111790 Type: PIT API Number: - Status: _____ Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 111791 Type: PIT API Number: - Status: _____ Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 210400 Type: WELL API Number: 045-06156 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 467552 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
For Pit Facility ID 111791, Operator shall comply with Rule 909.a and ensure that the Pit is properly permitted through a Form 15 approved by the Director, accurately mapped and listed according to current facility records in the Commission's database. Operators may update facility records using a Form 15. CA date: 5/30/2024	heilj	04/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403773983	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6530297
699700359	20240429 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6530292