

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2024

Submitted Date:

04/30/2024

Document Number:

708903662**FIELD INSPECTION FORM**

Loc ID 416887	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> ECMC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>33</u> Number of Comments <u>3</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417226	WELL	PR	06/06/2011	GW	045-19475	TWIN CREEK 1-16A1 (O1EB)	PR
417403	WELL	PR	06/21/2011	GW	045-19507	TWIN CREEK 1-10C2 (O1EB)	PR
417406	WELL	PR	05/09/2011	GW	045-19509	TWIN CREEK 12-1A1 (O1EB)	PR
417409	WELL	PR	06/18/2011	GW	045-19511	TWIN CREEK 1-9C1 (O1EB)	PR
417426	WELL	PR	07/12/2011	GW	045-19522	TWIN CREEK 1-16D1 (O1EB)	PR
417443	WELL	PR	05/09/2011	GW	045-19527	TWIN CREEK 12-2D1 (O1EB)	PR
417458	WELL	PR	08/04/2011	GW	045-19536	TWIN CREEK 1-10B1 (O1EB)	PR
417460	WELL	PR	05/09/2011	GW	045-19537	TWIN CREEK 1-15D1 (O1EB)	PR
417470	WELL	PR	06/21/2011	GW	045-19543	TWIN CREEK 1-9A1 (O1EB)	PR
417473	WELL	PR	01/01/2021	GW	045-19546	TWIN CREEK 1-9D1 (O1EB)	PR
417479	WELL	PR	05/09/2011	GW	045-19548	TWIN CREEK 12-2A1 (O1EB)	PR
417481	WELL	PR	08/04/2011	GW	045-19549	TWIN CREEK 1-10C1 (O1EB)	PR
417483	WELL	PR	05/09/2011	GW	045-19551	TWIN CREEK 12-1C1 (O1EB)	PR
417485	WELL	PR	06/11/2011	GW	045-19552	TWIN CREEK 12-1D1 (O1EB)	PR

417487	WELL	PR	04/01/2013	GW	045-19553	TWIN CREEK 12-2D2 (O1EB)	PR
--------	------	----	------------	----	-----------	--------------------------	----

**General Comment:**

CECMC Inspection Report Summary  
On 04/29/2024 at approximately 14:15 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at CAERUS PICEANCE LLC TWIN CREEK 1-10C2 (O1EB) Pad. Location # 416887 in Garfield County Colorado.  
Location is within High Priority/Density/NSO/Black Bear Habitat areas.  
Location is approximately 132 yards from East Divide Creek.  
Location is approximately 330 yards from West Divide Creek.  
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1. Signs/Marker - Wellhead signage insufficient/all wellhead signs lack required information with a CA date of 05/30/2024
- 2. Housekeeping - Tank on location is partially open & available for entry by wildlife/wildlife hazard with a CA date of 05/07/2024
- 3. Tanks & Berms - Earthen secondary containment damaged with a CA date of 05/20/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
This is a summary of inspection report.

Remote location/Split pad - production separators & tank battery located on the TWIN CREEK 1-15B (O1E) pad, location # 334939

<b>Location</b>				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Sign at entrance to location			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Wellhead signage insufficient/all wellhead signs lack required information/signs do not comply with CECMC rules			
Corrective Action:	Comply with CECMC signage rules		Date:	05/30/2024
Type	CONTAINERS			
Comment:	Chemical tanks			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911/970-285-2615			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:			Date:	
Type	OTHER			
Comment:	Tank is partially open & available for entry by wildlife/wildlife hazard			
Corrective Action:	Comply with CECMC wildlife rules & tank rules		Date:	05/07/2024
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Bradenhead	# 15			corrective date
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:			Date:	

Type: Ancillary equipment	# 4	
Comment:	Chemical tanks	
Corrective Action:		Date:
Type: Plunger Lift	# 15	
Comment:	All wells on plunger lift	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:	Roll top tank No telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	110 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Earthen secondary containment damaged/does not comply with CECMC secondary containment rules			
Corrective Action:	Comply with CECMC secondary containment rules			Date: 05/20/2024

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities						
Facility ID:	417226	Type:	WELL	API Number: 045-19475	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417403	Type:	WELL	API Number: 045-19507	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417406	Type:	WELL	API Number: 045-19509	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417409	Type:	WELL	API Number: 045-19511	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417426	Type:	WELL	API Number: 045-19522	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417443	Type:	WELL	API Number: 045-19527	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417458	Type:	WELL	API Number: 045-19536	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						
Facility ID:	417460	Type:	WELL	API Number: 045-19537	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12						

<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417470	Type:	WELL	API Number: 045-19543 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417473	Type:	WELL	API Number: 045-19546 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417479	Type:	WELL	API Number: 045-19548 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417481	Type:	WELL	API Number: 045-19549 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417483	Type:	WELL	API Number: 045-19551 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417485	Type:	WELL	API Number: 045-19552 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	417487	Type:	WELL	API Number: 045-19553 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing, well on plunger lift			

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank containments
		Compaction				
Retention Ponds						
Ditches						
		Culverts				
Rip Rap						
		Ditches				
Gravel						Sparse to none in some areas
Compaction						Large amount of light compaction in some areas
		Retention Ponds				
		Gravel				Sparse to none

Comment: [Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker, Housekeeping &amp; Tanks &amp; Berms for observed compliance issues.</a>	smelserw	04/30/2024
<a href="#">Remote location/Split pad - production separators &amp; tank battery located on the TWIN CREEK 1-15B (O1E) pad, location # 334939</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403774909	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531208">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531208</a>
708903664	Inspection 708903662 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531204">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531204</a>
708903665	Inspection 708903662 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531205">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531205</a>