

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/01/2024

Document Number:

699505762

## FIELD INSPECTION FORM

Loc ID 448754 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

## Operator Information:

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

## Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448753	WELL	PR	06/26/2018	OW	123-43996	JOHNSON 30N-14HZ	PR
448755	WELL	PR	06/26/2018	OW	123-43997	JOHNSON 4N-14HZ	PR
448756	WELL	SI	11/01/2023	OW	123-43998	JOHNSON 28C-14HZ	SI
448757	WELL	PR	06/26/2018	OW	123-43999	JOHNSON 29N-14HZ	PR
448758	WELL	PR	02/26/2019	OW	123-44000	JOHNSON 29C-14HZ	PR
448759	WELL	PR	06/27/2018	OW	123-44001	JOHNSON 4C-14HZ	PR
448760	WELL	PR	06/26/2018	OW	123-44002	JOHNSON 3N-14HZ	PR

## General Comment:

There have been no changes to equipment on location since previous inspection.

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					
Date: <input type="text"/>					
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

**Inspected Facilities**

Facility ID: 448753	Type: WELL	API Number: 123-43996	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448755	Type: WELL	API Number: 123-43997	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448756	Type: WELL	API Number: 123-43998	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448757	Type: WELL	API Number: 123-43999	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448758	Type: WELL	API Number: 123-44000	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448759	Type: WELL	API Number: 123-44001	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 448760	Type: WELL	API Number: 123-44002	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/12/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.  
 At time of inspection weather conditions were partly cloudy, warm, windy.

medinaj

05/01/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505763	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537343">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537343</a>