

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2024

Submitted Date:

05/01/2024

Document Number:

699505764

**FIELD INSPECTION FORM**Loc ID 317756 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239926	WELL	PR	09/01/2023	GW	123-07714	MARTIN J SCHAEFER 1	PR

**General Comment:**

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Prime Mover		# 1			
Comment:					
Corrective Action:				Date:	
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:		plumbed to surface			
Corrective Action:				Date:	
Type: Ancillary equipment		# 1			
Comment:		electric			
Corrective Action:				Date:	
Venting:					
Yes/No		NO			
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	239926	Type:	WELL	API Number:	123-07714	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:		05/08/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
ECMC Comments									
Comment						User		Date	
At time of inspection location appears to be in compliance with ECMC rules.						medinaj		05/01/2024	
At time of inspection weather conditions were partly cloudy, warm, windy.									
Attached Documents									
You can go to ECMC Images ( <a href="https://ecmc.state.co.us/weblink/">https://ecmc.state.co.us/weblink/</a> ) and search by document number:									
Document Num	Description			URL					
699505765	inspection pictures			<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537344">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537344</a>					