

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2024

Submitted Date:

05/02/2024

Document Number:

699505766

**FIELD INSPECTION FORM**

Loc ID 453934 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	<a href="#">ALL INSPECTIONS</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453935	WELL	DG	11/11/2023	LO	001-10104	EDMUNDSON 20N	WO
453937	WELL	PR	08/01/2021	OW	001-10106	Edmundson LE 33-082HC	PA
453942	WELL	DG	11/14/2023	LO	001-10111	EDMUNDSON 17C	WO
453947	WELL	DG	11/12/2023	LO	001-10116	EDMUNDSON 19C	WO
453950	WELL	DG	11/13/2023	LO	001-10119	Edmundson 18N	WO
453952	WELL	DG	11/17/2023	LO	001-10121	Edmundson 14N	WO
453953	WELL	DG	11/18/2023	LO	001-10122	Edmundson 13N	WO
453955	WELL	DG	11/15/2023	LO	001-10124	EDMUNDSON 16N	WO

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bradenhead # 8

Comment: Plumbed to surface

Corrective Action:

Date: \_\_\_\_\_

Type: VRU # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Gas Meter Run # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Bird Protectors # 4

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Emission Control Device # 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: LACT # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 1

Comment: automation / electric

Corrective Action:

Date: \_\_\_\_\_

Type: Pig Station # 1

Comment:

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 453935 Type: WELL API Number: 001-10104 Status: DG Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453937 Type: WELL API Number: 001-10106 Status: PR Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453942 Type: WELL API Number: 001-10111 Status: DG Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453947 Type: WELL API Number: 001-10116 Status: DG Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453950 Type: WELL API Number: 001-10119 Status: DG Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453952 Type: WELL API Number: 001-10121 Status: DG Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453953 Type: WELL API Number: 001-10122 Status: DG Insp. Status: WO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 453955 Type: WELL API Number: 001-10124 Status: DG Insp. Status: WO

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were clear, warm, light wind.	medinaj	05/02/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505767	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537345">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537345</a>