

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2024

Submitted Date:

05/02/2024

Document Number:

699505768

FIELD INSPECTION FORMLoc ID 434206 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434203	WELL	SI	11/01/2022	OW	123-38019	PETTINGER 30C-18HZ	SI
434204	WELL	PR	08/01/2023	OW	123-38020	PETTINGER 4C-18HZ	PR
434205	WELL	PR	09/01/2019	OW	123-38021	PETTINGER 4NE-18HZX	PR
434207	WELL	SI	11/01/2022	OW	123-38022	PETTINGER 30N-18HZ	SI
434208	WELL	SI	10/01/2023	OW	123-38023	PETTINGER 3N-18HZ	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

5

Comment: plumbed to surface

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: automation

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 434203 Type: WELL API Number: 123-38019 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434204 Type: WELL API Number: 123-38020 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434205 Type: WELL API Number: 123-38021 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434207 Type: WELL API Number: 123-38022 Status: SI Insp. Status: SI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434208 Type: WELL API Number: 123-38023 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 03/29/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were clear, warm, light wind.	medinaj	05/02/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505769	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6537346