

**Operator: HIGHPOINT OPERATING CORPORATION**

**Location Name: Coffelt 5-61-35\_36 NWNW**

**Loc ID: 439471**

**Inspection: 708201153**



**Exhibit A**



**Exhibit B**

**CA:** This location does not comply with Rule 1003. It was observed that interim areas are not progressing towards vegetative standards. While some desirable vegetation was observed in the northern areas, there is evidence of Russian thistle and kochia in the early growth stages throughout, and the southern portion of the interim areas consist mainly of Russian thistle. Operator will need to perform active weed management and continue to monitor the site until it reaches Rule 1003 standards and regulations. Refer to attached inspection photos. Comply with Rule 1003.

**CA Resolution:** Operator has reported that the location has been mowed, re-seeded, and crimped with straw mulch to encourage desired vegetation growth and to comply with Rule 1003.

**CA:** Old fence posts/h-brace located in the NE corner of the location remain from the initial location construction (e.g. before production equipment was moved to the south). Any fencing/posts that are not actively being used will need to be removed. Refer to attached inspection photos for additional. Comply with Rule 606 and remove any unused equipment.

**CA Resolution:** Operator has reported that identified unused fencing posts have been removed from location to comply with Rule 606.