

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2024

Submitted Date:

05/07/2024

Document Number:

709100290

FIELD INSPECTION FORM

Loc ID: 337789 Inspector Name: Heibel, Krystal On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kilian Collins		kilian.collins@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Abdul Elnajdi		abdul.elnajdi@state.co.us	
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288657	WELL	PR	08/01/2008	GW	125-10596	KNODEL 32-17	EI

General Comment:

On April 24, 2024, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, and Abdul Alnajdi inspected the Knodel32-17 location (Location ID:337789).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Tumbleweeds located within secondary containment.

Corrective Action: Comply with Rule 606

Date: 05/14/2024

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 288657 Type: WELL API Number: 125-10596 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100291	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539212