

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/08/2024

Document Number:

695109520

FIELD INSPECTION FORMLoc ID 307294 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|-------------------|---------------------------------|
| BACA, DAVE | 719-859-4066 | dbaca@ogrisop.com | All Inspections |
| WARD, GIENA | | gward@ogrisop.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 217405 | WELL | PR | 11/02/2007 | CBM | 071-06182 | GOLDEN EAGLE 34-03 | PR |
| 426747 | TANK BATTERY | AC | 04/14/2009 | | - | GOLDEN EAGLE-633S67W 34NENW | AC |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID.
PHOTO 6: AREA OF IMPACTED SOIL NEAR PUMPJACK SKID.

Corrective Action:

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.

Date: 06/08/2024Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Compressor

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: PHOTO 7: NO CURRENT CALIBRATION LOG POSTED AT METER.

Corrective Action: PROVIDE AREA FIELD INSPECTOR (@ tombeardslee@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION.

Date: 06/08/2024

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|--------------------|---|----------|-----------|---------|----------------------|--|
| PRODUCED WATER | 1 | <50 BBLS | STEEL AST | | 37.134880,104.878660 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 30BBL | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| | | | | | |
| Comment: | NO BURMS | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|--|
| Type | | |
| Comment: | | |
| Corrective Action: | | |

| Inspected Facilities | | | | | | | | | |
|--|--------|----------------------------|------|------------------------|-----------|-------------|----|---------------|----|
| Facility ID: | 217405 | Type: | WELL | API Number: | 071-06182 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | 07/18/2023 | | Annual Brhd Completed? | | | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | 0 | | Fluid Type: | | | |
| | | End Surf Csg Pressure: | | 0 | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 426747 | Type: | TANK | API Number: | - | Status: | AC | Insp. Status: | AC |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment: PHOTO 8: OILY WASTE IN ENGINE SKID.

Corrective Action: COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.

Date: 05/09/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 427015 | 200334636 | |
| | 427015 | 200334636 | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------|---|
| 695109521 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6541294 |