

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2024

Submitted Date:

05/02/2024

Document Number:

698601998

FIELD INSPECTION FORM

Loc ID: 303593 Inspector Name: St John, William (Cal) On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253332	WELL	PR	12/29/1986	GW	125-07209	TUELL 35 4	PR

General Comment:

Inspector is completing Follow-up inspection as required by FIRR. Follow-up inspection will ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 10/16/2023 FIR document number 698601164.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tankis faded and weathered. Colors not identifiable at reasonable distance.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/23/2023
	Corrective action date remains the same to document period of non-compliance.		
Type	WELLHEAD		
Comment:	Lease sign label is peeling.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Well location lease sign label is peeling and label needs to be replaced.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____
 Comment: _____
 Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Tank has a hole at grade level (Left of contents label) and a split in the fiberglass wall (backside) making it unuseable. No signage indicating tank is empty and out of service. Tank needs to be repaired, replaced, or removed.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.	Date:	11/23/2023		
	Corrective action date remains the same to document period of non-compliance.				

Paint			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 253332 Type: WELL API Number: 125-07209 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403777673	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534011
698602016	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6534001