

**Inspection Photos**  
**Location Name: C. Korf 2-19**  
**API Number: 125-06977**



**1. Sign bracket missing sign from 7/27/2023 inspection.**



**2. Replaced well lease sign.**

**Inspection Photos**  
**Location Name: C. Korf 2-19**  
**API Number: 125-06977**



**3. View of water leg leaking at valve and hammer union  
7/27/2023 inspection.**



**4. Closer view of hammer union and valve 7/27/2023  
inspection.**

**Inspection Photos**  
**Location Name: C. Korf 2-19**  
**API Number: 125-06977**



**5. Wet area at wells water leg inside and outside fencing  
7/27/2023 inspection.**



**6. View of removed pipe section and fittings on water leg.**

**Inspection Photos**  
**Location Name: C. Korf 2-19**  
**API Number: 125-06977**



**7. View of continued water seep at valve and plug.**



**8. Damp soil and salt ring around riser with seep at valve and plug.**