

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 1 Location.



Photo 2 Wellsite.

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 3 WH sign.



Photo 4 WH.

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 5 Gas engine is not operational due to the alternator being disconnected.



Photo 6 TB Location.

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 7 ECD.



Photo 8 Horizontal Heated separator.



Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 9 Flow line manifold.



Photo 10 Vertical Separator at the recirculation pump.

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 11 Recirculation pump partially enclosed by 3 sound walls.



Photo 12 Recirculation pump partially enclosed by 3 sound walls.

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 13 Recirculation pump Missing the panel on the north side of the pump.



Photo 14 Side panel set on top of the pump housing.

Inspection Photos
Location Name: Zarlengo B 1
Location ID: 320326



Photo 15 TB sign.



Photo 16 TB.