

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2024

Submitted Date:

05/13/2024

Document Number:

693807314

**FIELD INSPECTION FORM**Loc ID: 314953 Inspector Name: BROWNING, CHUCK On-Site Inspection: ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10725

Name of Operator: VALKYRIE OPERATING LLC

Address: 1600 STOUT STREET SUITE 1000

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
Dunham, Tyson	(307)388-2290	tdunham@valkyrie-resources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229951	WELL	IJ	03/01/2021	ERIW	103-07610	GOVERNMENT C-1041 3	SI

**General Comment:**

Routine UIC inspection.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign at location entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-347-3737

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Injection wellhead inside housing		
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 229951

Type: WELL

API Number: 103-07610

Status: IJ

Insp. Status: SI

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube: Pressure or inches of Hg 830

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBR

TC: Pressure or inches of Hg 120

Previous Test Pressure

Last MIT: 08/11/2023

Brhd: Pressure or inches of Hg 0

Previous Test Pressure

AnnMTReq:

Comment:

Routine UIC Inspection. Well shut in. No active injection at time of inspection.

Corrective Action:

Date:

Method of Injection: PUMP FEED

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807315	Inspection photos 5/10/2024	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546446</a>