

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2024

Submitted Date:

05/13/2024

Document Number:

710500271

**FIELD INSPECTION FORM**Loc ID 324797 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	
Hart, Dale	719-688-1638	dale@westernoperating.com	
Costa, Ryan		ryan.costa@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212663	WELL	PR	11/01/2023	OW	061-06023	DAWSON A 1	EI
324797	LOCATION	AC			-	DAWSON A-619S45W 9NENW	EI
481653	SPILL OR RELEASE	CL	03/14/2022		-	Dawson A 1 tank battery	EI

**General Comment:**

This is a follow up Environmental Inspection for the Dawson A-1; Location ID # 324797, active well location and Tank Battery, located in Kiowa County, Co. There is an ongoing Remediation, Remediation # 20712 between the tank battery and well location.

Location				
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	There is a new sign posted at the tank battery.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign at wellhead is missing Operator information. Update sign to reflect Operator name and emergency number.  Update and maintain signage to comply with Rule 605.g.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

### Location Construction

Location ID: 324797 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Comment: At the time of inspection there were no stormwater BMPs surrounding the open excavation or protecting loose soils.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 06/10/2024

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_



**Environmental****Spill/Remediation:**

Comment: Remediation Project #20712 remains ongoing and excavation has been open for more than 12 months. There are still areas of oil stained soil in the excavation that need to be cleaned up. Additional excavation is needed to remove contaminated soils.

Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area

Corrective  
Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
Remediation Project #20712 remains ongoing and excavation has been open for more than 12 months. There are still areas of oil stained soil in the excavation that need to be cleaned up. Additional excavation is needed to remove contaminated soils.	sanchezcc	05/13/2024
Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area		
All previously, assigned CAs shall apply	sanchezcc	05/13/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500272	Inspection # 710500271 Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546486">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6546486</a>