

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2024

Submitted Date:

05/08/2024

Document Number:

708302139

**FIELD INSPECTION FORM**

|  |                                    |   |                   |   |
|--|------------------------------------|---|-------------------|---|
| Loc ID<br>422301   | Inspector Name:<br>Morris, Matthew | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>12 Number of Comments<br>2 Number of Corrective Actions<br><input checked="" type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>ECMC Operator Number: 96850<br>Name of Operator: TEP ROCKY MOUNTAIN LLC<br>Address: 1058 COUNTY ROAD 215<br>City: PARACHUTE State: CO Zip: 81635 |                                    |   |                   | <b>ANY CORRECTIVE ACTION(S) FROM<br/>PREVIOUS INSPECTIONS THAT HAVE NOT<br/>BEEN ADDRESSED ARE STILL APPLICABLE</b>   |

| <b>Contact Information:</b> |       |                                    |         |
|-----------------------------|-------|------------------------------------|---------|
| Contact Name                | Phone | Email                              | Comment |
| , TEP                       |       | COGCCInspectionReports@terraep.com |         |

| <b>Inspected Facilities:</b> |      |        |             |            |           |                  |             |
|------------------------------|------|--------|-------------|------------|-----------|------------------|-------------|
| Facility ID                  | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
| 422303                       | WELL | PR     | 07/13/2015  | GW         | 045-20549 | BAT 24A-24-07-96 | PR          |
| 422306                       | WELL | PR     | 11/26/2013  | GW         | 045-20550 | BAT 32B-24-07-96 | PR          |
| 422309                       | WELL | PR     | 03/01/2021  | GW         | 045-20553 | BAT 12A-24-07-96 | PR          |
| 422313                       | WELL | PR     | 12/01/2022  | GW         | 045-20556 | BAT 13D-24-07-96 | PR          |
| 422322                       | WELL | PR     | 01/01/2023  | GW         | 045-20562 | BAT 12B-24-07-96 | PR          |
| 432749                       | WELL | PR     | 11/26/2013  | GW         | 045-22044 | BAT 32C-24-07-96 | PR          |
| 433580                       | WELL | PR     | 11/06/2014  | GW         | 045-22092 | BAT 34A-24-07-96 | PR          |
| 433596                       | WELL | PR     | 04/21/2014  | GW         | 045-22093 | BAT 13A-24-07-96 | PR          |
| 433602                       | WELL | PR     | 05/07/2014  | GW         | 045-22094 | BAT 33C-24-07-96 | PR          |
| 433603                       | WELL | PR     | 04/21/2014  | GW         | 045-22095 | BAT 12C-24-07-96 | PR          |
| 433610                       | WELL | PR     | 04/21/2014  | GW         | 045-22097 | BAT 33B-24-07-96 | PR          |
| 433611                       | WELL | PR     | 08/26/2014  | GW         | 045-22098 | BAT 13C-24-07-96 | PR          |
| 433638                       | WELL | PR     | 04/21/2015  | GW         | 045-22100 | BAT 32D-24-07-96 | PR          |
| 433643                       | WELL | PR     | 04/30/2014  | GW         | 045-22102 | BAT 33A-24-07-96 | PR          |
| 433662                       | WELL | PR     | 09/01/2023  | GW         | 045-22105 | BAT 32A-24-07-96 | PR          |
| 433665                       | WELL | PR     | 04/30/2014  | GW         | 045-22106 | BAT 12D-24-07-96 | PR          |
| 433666                       | WELL | PR     | 12/01/2022  | GW         | 045-22107 | BAT 33D-24-07-96 | PR          |
| 433668                       | WELL | PR     | 05/01/2022  | GW         | 045-22108 | BAT 13B-24-07-96 | PR          |
| 437236                       | WELL | PR     | 04/16/2015  | GW         | 045-22416 | BAT 34B-24-07-96 | PR          |
| 437237                       | WELL | PR     | 04/21/2015  | GW         | 045-22417 | BAT 34D-24-07-96 | PR          |
| 437238                       | WELL | PR     | 04/18/2015  | GW         | 045-22418 | BAT 24C-24-07-96 | PR          |

|        |      |    |            |    |           |                  |    |
|--------|------|----|------------|----|-----------|------------------|----|
| 437239 | WELL | PR | 04/11/2015 | GW | 045-22419 | BAT 24B-24-07-96 | PR |
| 437390 | WELL | PR | 05/14/2015 | GW | 045-22424 | BAT 34C-24-07-96 | PR |
| 437391 | WELL | PR | 05/11/2015 | GW | 045-22425 | BAT 24D-24-07-96 | PR |

**General Comment:**

COGCC Inspection Report Summary

On 5/7/2024 at approximately 13:30, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, Speakman/A Pad at Location ID #422301 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Debris on location
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | CONTAINERS   |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | BATTERY  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | OTHER  |       |  |
| Comment:           | Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank. |       |  |
| Corrective Action: |  | Date: |  |
| Type               | TANK LABELS/PLACARDS   |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Emergency Contact Number:**

Comment: 911/(970) 285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | DEBRIS  |       |            |
| Comment:           | Debris on east side of location near access road. |       |            |
| Corrective Action: | Remove debris to comply with Rule 606.            | Date: | 05/28/2024 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |                   |       |  |
|--------------------|-------------------|-------|--|
| Type               | LOCATION          |       |  |
| Comment:           |                   |       |  |
| Corrective Action: |                   | Date: |  |
| Type               | WELLHEAD          |       |  |
| Comment:           | Livestock corrals |       |  |
| Corrective Action: |                   | Date: |  |

|                           |                |  |  |                 |
|---------------------------|----------------|--|--|-----------------|
| <b>Equipment:</b>         |                |  |  | corrective date |
| Type: Bradenhead          | # 20           |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Plunger Lift        | # 20           |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Plunger Lift        | # 4            |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Bird Protectors     | # 14           |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Other               | # 1            |  |  |                 |
| Comment:                  | Line heater    |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Bradenhead          | # 5            |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Ancillary equipment | # 5            |  |  |                 |
| Comment:                  | Chemical tanks |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Gas Meter Run       | # 5            |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |
| Type: Gas Meter Run       | # 20           |  |  |                 |
| Comment:                  |                |  |  |                 |
| Corrective Action:        |                |  |  | Date:           |

**Tanks and Berms:**

| Contents           | # | Capacity | Type             | Tank ID | SE GPS |       |
|--------------------|---|----------|------------------|---------|--------|-------|
| PRODUCED WATER     | 1 | 500 BBLs | HEATED STEEL AST |         | ,      |       |
| Comment:           |   |          |                  |         |        |       |
| Corrective Action: |   |          |                  |         |        | Date: |

**Paint**

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

**Berms**

|      |          |                     |                     |             |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|

Inspector Name: Morris, Matthew

|                    |          |                     |                     |             |        |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |
| CONDENSATE         | 2        | 300 BBLs            | HEATED STEEL AST    |             | ,      |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Paint</u>       |          |                     |                     |             |        |
| Condition          | Adequate |                     |                     |             |        |
| Other (Content)    |          |                     |                     |             |        |
| Other (Capacity)   |          |                     |                     |             |        |
| Other (Type)       |          |                     |                     |             |        |
| <u>Berms</u>       |          |                     |                     |             |        |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS |
| PRODUCED WATER     | 5        | 400 BBLs            | STEEL AST           |             | ,      |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Paint</u>       |          |                     |                     |             |        |
| Condition          | Adequate |                     |                     |             |        |
| Other (Content)    |          |                     |                     |             |        |
| Other (Capacity)   |          |                     |                     |             |        |
| Other (Type)       |          |                     |                     |             |        |
| <u>Berms</u>       |          |                     |                     |             |        |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Venting:</u>    |          |                     |                     |             |        |
| Yes/No             | NO       |                     |                     |             |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |
| <u>Flaring:</u>    |          |                     |                     |             |        |
| Type               |          |                     |                     |             |        |
| Comment:           |          |                     |                     |             |        |
| Corrective Action: |          |                     |                     |             | Date:  |

| Inspected Facilities   |        |       |      |   |
|--|--------|-------|------|---|
| Facility ID:   | 422303 | Type: | WELL | API Number: 045-20549 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 422306 | Type: | WELL | API Number: 045-20550 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 422309 | Type: | WELL | API Number: 045-20553 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 422313 | Type: | WELL | API Number: 045-20556 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 422322 | Type: | WELL | API Number: 045-20562 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 432749 | Type: | WELL | API Number: 045-22044 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 433580 | Type: | WELL | API Number: 045-22092 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |
| Facility ID:   | 433596 | Type: | WELL | API Number: 045-22093 Status: PR Insp. Status: PR |
| <b>Producing Well</b>  |        |       |      |   |
| Comment:   |        |       |      |   |
| Corrective Action:   |        | Date: |      |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |      |   |

| <u>Producing Well</u>  |        |       |       |   |
|--|--------|-------|-------|---|
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433602 | Type: | WELL  | API Number: 045-22094 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433603 | Type: | WELL  | API Number: 045-22095 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433610 | Type: | WELL  | API Number: 045-22097 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433611 | Type: | WELL  | API Number: 045-22098 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433638 | Type: | WELL  | API Number: 045-22100 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433643 | Type: | WELL  | API Number: 045-22102 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |
| Corrective Action:   |        |       | Date: |   |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |       |   |
| Facility ID:   | 433662 | Type: | WELL  | API Number: 045-22105 Status: PR Insp. Status: PR |
| <u>Producing Well</u>  |        |       |       |   |
| Comment:   |        |       |       |   |

|  |           |         |      |
|--|-----------|---------|------|
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 433665    | Type:   | WELL |
| API Number:  | 045-22106 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 433666    | Type:   | WELL |
| API Number:  | 045-22107 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 433668    | Type:   | WELL |
| API Number:  | 045-22108 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 437236    | Type:   | WELL |
| API Number:  | 045-22416 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 437237    | Type:   | WELL |
| API Number:  | 045-22417 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 437238    | Type:   | WELL |
| API Number:  | 045-22418 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |
| Facility ID:   | 437239    | Type:   | WELL |
| API Number:  | 045-22419 | Status: | PR   |
| Insp. Status:  | PR        |         |      |
| <b>Producing Well</b>  |           |         |      |
| Comment:   |           |         |      |
| Corrective Action:   |           | Date:   |      |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |           |         |      |

|  |            |                       |            |                  |
|--|------------|-----------------------|------------|------------------|
| Facility ID: 437390  | Type: WELL | API Number: 045-22424 | Status: PR | Insp. Status: PR |
| Producing Well   |            |                       |            |                  |
| Comment:   |            |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
| Facility ID: 437391  | Type: WELL | API Number: 045-22425 | Status: PR | Insp. Status: PR |
| Producing Well   |            |                       |            |                  |
| Comment:   |            |                       |            |                  |
| Corrective Action:   |            |                       |            | Date:            |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |            |                       |            |                  |
|  |            |                       |            |                  |

Date Run: 5/15/2024 Doc [#708302139]Page 9 of 10

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                                  |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--|
| Sediment Traps   |                 |                         |                       |  |                          |  |
|                  |                 | Culverts                |                       |  |                          |  |
| Gravel           |                 |                         |                       |  |                          |  |
|                  |                 | Ditches                 |                       |  |                          |  |
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          | Chemical tanks in secondary containment  |
| Tracking Pad     | Fail            |                         |                       |  |                          | Tracking pad location is not serviceable |
| Berms            |                 |                         |                       |  |                          |  |
|                  |                 | Compaction              |                       |  |                          |  |
|                  |                 | Gravel                  |                       |  |                          |  |
| Ditches          |                 |                         |                       |  |                          |  |
| Other            | Fail            |                         |                       |  |                          | Insufficient tracking BMPs               |
| Compaction       | Fail            |                         |                       |  |                          | Lack of stabilization                    |

Comment: Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment. Tracking pad is not installed in serviceable location.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/10/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403784446    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6541252">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6541252</a> |
| 708302140    | Photo Log            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6541251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6541251</a> |